

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

U.S. NAVAL BASE, PEARL HARBOR, BAKER DOCKS B-11 TO
B-21

HAER HI-10

(U.S. Naval Base, Pearl Harbor, Naval Station)

(Wharfs, Bravo Docks B-11 to B-21)

North of Pearl Harbor Shipyard

Pearl Harbor

Honolulu County

Hawaii

INDEX TO BLACK AND WHITE PHOTOGRAPHS

David Franzen, photographer, October 2005

- | | |
|---------|---|
| HI-10-1 | Oblique view of B-11 looking toward the end of the pier. View facing northeast |
| HI-10-2 | Elevation of the end of pier B-11/B-12. View facing southwest |
| HI-10-3 | Oblique view of B-12/B-13. The end of the pier is out of view on the right. View facing southwest |
| HI-10-4 | Oblique view of B-12/B-13 looking toward the end of the pier. View facing northeast |
| HI-10-5 | Oblique view of B-14. Note the lowered area near the water line. View facing southeast |
| HI-10-6 | Oblique view of B-15/B-16. The end of the pier is at the left. View facing southwest |
| HI-10-7 | Oblique view of B-17/B-18, with B-17 at the right. The end of the pier is at the right. View facing southwest |
| HI-10-8 | Oblique view of B-17/B-18. Looking toward the end of the pier, which is on the right. View facing northeast |
| HI-10-9 | Oblique view of B-19. Note the area that is lowered near the water line. View facing south-southeast |

U.S. NAVAL BASE, PEARL HARBOR, BAKER DOCKS B-11

HAER HI-10
INDEX TO PHOTOGRAPHS

Page 2

HI-10-10	Elevation of the center portion of B-19 showing the lowered area. Note the original awning windows. View facing southwest
HI-10-11	Oblique view of B-19. View facing west
HI-10-12	Oblique view of B-21 with the end of the wharf in the foreground. View facing southwest
HI-10-13	Deck surface of B-11. Looking toward the end of the pier. View facing northeast
HI-10-14	Deck surface of B-13. Looking toward the base of the pier. View facing southwest
HI-10-15	Detail of timber fender system at B-13. View facing northwest
HI-10-16	Deck surface of B-13. Note the tracks for the portal crane and the asphalt strip which was the former location of tracks for the railroad. View facing northeast
HI-10-17	Deck surface of B-14. Note the stairway railing to the lowered area. The large structure in the center is Navy vessel YRBM-37, a repaid, berthing, and messing barge that is docked at B-14. View facing northwest
HI-10-18	Deck surface of B-21. Building No. 72 on the right. Note the tracks for the portal crane and asphalted areas of former track for the railroad. View facing northeast
HI-10-19	Deck surface of B-21 looking toward the end of wharf. Showing the former railroad tracks. View facing northeast
HI-10-20	Detail of the end of Wharf B-21. View facing southeast
HI-10-21	Deck surface at the end of Wharf B-21. Showing the stairwell down to small craft landing area below the deck. View facing northwest

U.S. NAVAL BASE, PEARL HARBOR, BAKER DOCKS B-11 TO B-21
(U.S. Naval Base, Pearl Harbor, Naval Station)
(Wharfs, Bravo Docks B-11 to B-21)
HAER No. HI-10
Index to Photographs (Page 3)

Photo Key

